

Company Gas & Oil Operations

Farm Chas. Knabe

No. 1

Sec. 10 T. 14 R. 22E

Loc. S₂¹-SE₄¹

County Johnson

Total Depth 726'

Comm. 9-9-60

Comp. 9-14-60

Shot or Treated

Contractor

Issued


Casing

20 in. 10 in

15 1/2 8 1/4

12 1/2 6 5/8

13 3/8 5 3/16



Elevation

Production

Figures Indicate Bottom of Formation

Soil & Clay	12	Shale	700.80
Lime	16	Lime	702.80
Shale	22	Shale	703.80
Lime	38	Shale	707.20
Shale	45	Shale	710.30
Lime	55	Shale	711.30
Shale	58	Oil sand soft	713.30
Lime	76	Sand, hard	715.00
Shale	102	Sand good, hard	717.65
Lime	170	Oil-sand	720.35
Shale	209	Sandy Shale	723
Lime	216	Shale	726
Shale	235		TOTAL DEPTH 726'
Lime	242		
Shale	246		
Lime	255		
Shale	286		
Lime	287		
Shale	297		
Lime	304		
Shale	307		
Lime	324		
Shale	330		
Lime	353		
Shale	357		
Lime	360		
Shale	366		
Lime	373		
Shale	546		
Lime	550		
Shale	562		
Lime	566		
Shale	585		
Lime	589		
Sandy shale	598	Good gas	
Lime	599		
Shale	605		
Lime	608		
Shale	697.30		
Lime	690.30		
Shale	697.50		