

*Plotted
 Hand.
 11-14-22E*


O.K. SUPPLY CO.
 T. E. Moore No. 1.

SEC. 11 T. 14 R. 22E.
 SE SW SW
 160' N 1200 E of SWc

CORRECTED LOG.

County. Johnson.

Total Depth. 903
 Comm. 8-23-39 Comp. 9-6-39
 Shot or Treated.
 Contractor.
 Issued. 8-2-40



CASING.

10" 17'

Elevation. 1043 ± 3 1690

Production. DRY.

Figures Indicate Bottom of Formations.

clay	17	shale	712
lime	22	sand oil	717 show oil 717 <i>Sy</i>
shale	29	shale	735
lime	46	shale dark	740
shale	53	lime	743
lime	62	shale	760
shale	70	shale	825
lime	85	lime broken	826 small show oil 826
shale	106	sdv shale	836
lime	180	sand	841 small show oil 841 <i>Ev</i>
shale	213	sdv shale	885
limo	222	sand	903
shale	241		
lime	249	Total Depth.	
shale	251		
lime	262	Top of Hertha	377
shale	292		
lime	295		
shale	303		
lime	335		
shale	337		
lime	360		
shale	362		
lime	366		
shale	371		
lime	377		
shale	435		
lime	439		
shale	554		
lime	559		
shale	534		
limo	568		
shale	539		
lime	570		
shale	536		
lime	590		
shale blk	595		
lime	597		
shale	600		
lime	605		
red rock	615		

Base KC

lime	623
shale blk	626
shale	685
shale blk	701
broken limo	702

75,000 gas. *FS*