## 11-15-1E

## WELL LOG BUREAU—KANSAS GEOLOGICAL SOCIETY Wichita, Kansas 508 East Murdock,

Company. F.W. VISHNEFSKE Farm- Robson

Greenland Drlg. Co.

1

Comp. 11-11-57

11 7. 15 SEC. NW NE NW

County Dickinson

KANSAS @

R. 1E

CASING:

12-28-57

8\_5/8" 1401 2410

Total Depth. 2417

Comm. 11-5-57 Shot or Treated.

Contractor.

issued.

Elevation. 1217 RB

 $\mathbf{D_{ry}}$ Production.

Figures Incicate Bottom of Formations.

shale-clay 90 lime-shale 140 lime-shale w/red bed stks 230 shale-lime 1555 lime 1605 shale-lime 1756 brn lime-shale 1760 shale-lime 2409 Mississippi

2415 RTD 2417

Mississippi Total Depth

TOPS:

Lansing 1790 Weathered Mississippi2410 Mississippi 2415

Top of Mississippian was encountered @ 2409 w/good oil show and good odor. Drilled in 91, still oil and better porosity. Casing was set @ 2409 w/Cmtrl. Float show which did not hole, and hole filled up. After drilling out cement and swabbing, we got quantity of extremely heavy oil and wtr broke in at bottom. Well was abandoned because of heavy oil and wtr. problem.