

Company Hughes

Farm Robert Watson

No. 2

5-15-22C  
Sec. 5 T. 15 R. 22E

Loc. E/2 SE

County Johnson


Total Depth 910 ft.

Comm.

Shot or Treated

Contractor

Issued

Comp. Not known, but between  
1960 and 1966. 2

## Casing

|        |        |
|--------|--------|
| 20 in. | 10 in  |
| 15 1/2 | 8 1/4  |
| 12 1/2 | 6 5/8  |
| 13 3/8 | 5 3/16 |

Elevation

Production

Figures Indicate Bottom of Formation

Soil&amp;Clay 13

Lime 3

Shale 3

Lime 7

Lime 6

Lime 9

Shale 14

Sand 15

Sand&amp;Lime 31

Shale 9

Sand 7

Sand 3

Shale sdy 11

Sand 5

Sand 5

Lime sdy 6

Shale 8

Shale 4

Lime 7

Shale 5

Lime 11

Shale 20

Lime 5

Shale 3

Lime 7

Shale 34

Lime 3

Shale 11

Lime 23

Shale 6

Lime 23

Shale 3

Lime 6

Shale 9

Lime 6

Shale 5

Sand 15

Shale 82

Sand 5

Shale 58

13

16 rock

19

26

32 shale

41

55 lite

70 water

101 very hard

110 blue

117

120 firm

131

136 limey

141 water

147

155 blue

159 blue

166 very hard

171 blue

182 very hard

202 blue

207

210 blue

217

251

254

265 blue

288

294 gray

317

320 water 5 1/2 Baler @ hr.

326

335 slm

341 very hard bottom

of Hergetha

346 blue

361

443

448 oil sh

506

Lime

Shale

Lime

Shale

Shale

Lime

Slate

Lime

Shale

Red Bed

Shale

Lime

Shale

Shale

Sand

Shale

Sand

Big gas 100# in 12 min.

Shale

Shale

Sand

Shale

Sand

Sand

Shale

Sand

Limey

Lots of water

T.D. 910 ft.

March 31, 1964

514

526 blk

532

545 lite

550 drk

555

558 blk

570

575

579

590 drk

592

650 white

668 drk

680 gas

788

806 gas 151,000 cu. ft.

City Service test

845 some gas

850 sdy

865

870 blk

880 blk

888 lite

895

905 Burggess

910 some sand