

22-15-23E

Company Earl Mauldin

Sec. 22 T. 15S R. 23E.

Farm Mauldin

Loc. NE SE NW

No. 1

County Miami

Drilling record shows hole @ E/2NW

Total Depth 850

Comm. 6/4/1949


Comp. 6/16/49

Shot or Treated

Plugged 8/16/1949

Contractor

Issued



Elevation

Production D & A

Casing

| | |
|--------|--------|
| 20 in. | 10 in |
| 15 1/2 | 8 1/4 |
| 12 1/2 | 6 5/8 |
| 13 3/8 | 5 3/16 |

4 7/8" 787'

Figures Indicate Bottom of Formation

| | | | |
|-------------------------|---------------------|--------------|----------|
| Soil | 3 | Shale | 657 |
| Lime <i>crystalline</i> | 12 | Lime | 659 |
| Shale | 16 | Shale, sandy | 685 |
| Shale | 20 | Shale | 695 |
| Lime | 28 | Lime | 697 |
| Shale | 36 | Shale | 722 |
| Lime | 60 | Sand | 727 |
| Shale | 72 | Shale | 752 |
| Lime | 86 | Lime | 754 |
| Shale | 178 | Shale | 757 |
| Lime | 201 | Shale | 822 |
| Shale, brkn | 210 | Lime | 823 |
| sand ? | 218 | Shale | 832 |
| Shale | 223 | Shale | 850 T.D. |
| ? <i>limestone</i> ? | 228 | | |
| Shale | 244 | | |
| Lime | 249 | | |
| Shale | 255 | | |
| Shale | 262 | | |
| Lime | 264 | | |
| Shale | 279 | | |
| Lime | 282 | | |
| Shale | 293 | | |
| Sand | 296 | | |
| Shale | 297 | | |
| Lime | 322 | | |
| Shale | 326 | | |
| Lime | 247 | | |
| Shale | 350 | | |
| Lime | 372 | | |
| Shale | 376 | | |
| Sand | 380 | | |
| Shale | 490 <i>(or 390)</i> | | |
| Shale | 582 | | |
| Lime | 583 | | |
| Shale | 587 | | |
| Lime | 595 | | |
| Shale | 598 | | |
| Lime | 608 | | |
| Lime | 611 | | |
| Shale | 647 | | |
| Lime | 649 | | |

*Lithographic
km ?*