

34-16-19E

Company Chas. Judd

Sec. 34 T. 16 R. 19
Loc.

Farm Moore

No. 2

Total Depth 765

Comm. 4/25/32


Comp.

County Franklin

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	
12 1-2	6 5-8	632
13 3-8	5 3-16	

Elevation 860

Production Dry Hole

Figures Indicate Bottom of Formation

	<i>Thick</i>		<i>Thick</i>		
soil	4	4	2	gy shale	601
sand & clay	18	22	1	lime	602
lime	22	44	5	gy shale	607
blk shale	4	48	2	lime	609
lime	6	54	3	blk slate	612 gas bubbles
gy shale	6	60	2	gy sha e	614
lime	17	77	12	lime	626
red rock	3	80	10	gy shale	636
gy shale	152	232	3	blk shale	639
lime	29	261	4	lime	643
gy shale	9	270	8	blk shale	651
red rock	5	275	3	lime	654
lime	6	281	13	l shale	667
shale	17	298	1	lime	668
red rock	3	301	5	gy shale	673
gy shale	4	305	4	dk shale	677
lime	17	322	10	l shale	687
gy shale	21	343	5	lime shale	692 lime shells
lime	7	350	18	l shale	710
blk slate	3	353	10	gy shale	720
lime	13	366	15	dk shale	735
dk shale	8	374	1	sdylime	735
lime	26	400	4	dk shale	740
blk shale	2	402	3	blk shale	743
lime	9	411	3	lime	746 plugged here
l shale	5	416	2	shale	748
sand	21	437	2	sand	750 show of gas
gy shale	10	447	15	sand and lime	765 T.D.
sand	20	467			
broken sand	13	480			
gy shale	58	538			
l shale	33	571			
lime	10	581			
gy shel	5	586			
lime	11	597			
blk slate	2	599			