

Entered by Herbert Peterson

34-16-19E

Company Chas. Judd et al

Sec. 34 T. 16 R. 19

Farm Stucken

No. 1

Loc. 180 SW 1/4, 2' W.L., SW 1/4

SW SW SW - KGS - DPL

Total Depth 760

County Franklin

NA083 LEO

Comm. 10/1/32


Comp. 10/8/32

WLB 06/19/23

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.
15 1-2	8 1-4
12 1-2	6 5-8
13 3-8	5 3-16

665

Elevation 860

Production Dry Hole

Figures Indicate Bottom of Formation

soil	4	4
river mud	23	27
river gravel	4	31
lime	22	53
dk shale	4	57
lime	10	67
gy shale	6	73
lime	16	89
gy shale	2	91
ed bed	5	96
gy shale	145	241
lime	25	266
gy shale	19	285
lime	5	290
gy shale	4	294
ed bed	5	299
shale	10	309
red bed	4	313
gy shale	5	318
lime	16	334
dk shale	2	336
lime	2	338
dk shale	15	353
lime	8	361
blk shale	2	363
lime	12	375
blk shale	9	384
lime	26	410
blk shale	2	412
lime	11	423
gy shale	5	428
sand	6	434
l shale	24	458
sand	20	478
ro. sand	17	495
dy shale	55	550
sand	10	560 broken
gy shale	23	583
lime	4	587
sd shale	12	599

lime	11	610
blk shale	2	612
gy shale	2	614
lime	1	615
gy shale	5	620
glk shale	3	623
gy shale	3	626
lime	9	635
gy shale	4	641
blk shale	4	649
lime	8	653
blk shale	4	661 gas bubbles
gy shale	4	665 2nd 6 1/2 pipe
lime	4	669
l shale	8	677
lime	2	679
blk shale	13	692
l shale	23	715
dk shl	25	740
lime	1	741
dk shale	11	752
sand	7	759 broken show oil
sd shale	1	760 T.D.