


24-16-20E
7

plotted
dcs.

Location _____



Sec. 27, T. 16, R. 20 ^E_W

Farm Eastdale

No. 1

County FRANKLIN

Company _____

Commenced _____ Completed _____

Elevation _____ T.D. _____ I. P. Line

Through line at 330
water 550

Top of gas 627.642
break

Sand 644-648 $\frac{1}{2}$ - a PLOTTED LOG ONLY no log available
little water

Drilled 1920