

Plotted *Green* 17-16-218

Company Texas

Sec. 17 T. 16 R. 21
Loc. S₁ SE₁

Farm W.E.Shelton

No. 15

County Franklin

Total Depth 790


Comm.

Comp. 7/16/26

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	10
15 1-2	8 1-4	
12 1-2	6 5-8	625
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Soil	10	Shale	352
Gravel	12	Lime	355
Lime	27	Shale	359
Shale	30	Lime	363
Lime	35	White Shale	375
Shale	38	Blue Slate	408
Lime	43	Lime	418
Shale (fr. water)	45	Blue Shale	420
Lime	55	Lime	423
Blue Slate	90	Big Shale	515
Lime	110	Lime	516
Shale	175	Shale	568
Lime	180	Lime	575
Blue Shale	190	Blue Shale	588
White Lime	212	Lime	590
Drk. Shale	218	Blk. Water	593
Lime	224	Lime	600
Blue Shale	234	Shale	610
Lime	240	Lime	615
Blue Shale	269	Shale	618
White Lime	271	Lime	622
Blue Shale	277	Shale	625
White Lime	279	Lime	629
Shale	297	White Shale	635
White Lime	298	Oil Sand	642
Shale	301	Broken Sand	680
Lime	303	Shale	704
Blue Shale	307	Sand	710
White Lime	320	Blue Shale	774
Shale	325	Sand Water	790 T.D.
Lime	350		