

20-16-21E

Company Texas

Sec. 20 T. 16 R. 21
Loc. NW $\frac{1}{4}$, NE $\frac{1}{4}$


Farm Belle Moherman

No. 9

County Franklin

Total Depth 682
Comm.
Shot or Treated
Contractor
Issued

Comp. 9/23/19



Casing

20 in.	10 in. 9
15 1-2	8 1-4 410
12 1-2	6 5-8 636
13 3-8	5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

Soil & Lime	18	Lime	330 #0?
Shale	28	Shale Blk.	355 (water)
Lime	30	Lime	360
Shale	40	Shale	410
Lime	45	Shale	515
Shale	70	Lime	525
Lime	100	Shale	575
Shale	110	Lime	580
Lime	120	Shale	590
Shale	195	Lime	595
Lime	215	Shale Blk. Sft.	605 (water)
Shale	235	Shale	630
Lime	240	Lime	635
Shale	265	Sand	636
Lime	270	Sand	672
Shale	275	Shale	682
Lime	280		
Shale	290		
Lime	320		
Shale	330		