

20-16-21E

Company Texas

Sec. 20

T. 16

R. 21

Loc.

E $\frac{1}{2}$  NW $\frac{1}{4}$ 

Farm Hahn &amp; Wood

No. 8

County Franklin

Total Depth 692


Comm.

Comp. 6/28/22

Shot or Treated

Contractor

Issued



Casing

|        |        |     |
|--------|--------|-----|
| 20 in. | 10 in. | 14  |
| 15 1-2 | 8 1-4  | 385 |
| 12 1-2 | 6 5-8  | 630 |
| 13 3-8 | 5 3-16 |     |

Elevation

Production

Figures Indicate Bottom of Formation

|             |     |             |     |
|-------------|-----|-------------|-----|
| Soil        | 7   | Broken Lime | 530 |
| Lime        | 80  | Shale       | 540 |
| Shale       | 103 | Lime        | 547 |
| Lime        | 132 | White Shale | 553 |
| Shale       | 203 | Blue Shale  | 595 |
| Lime        | 230 | Lime        | 603 |
| Shale       | 251 | Blk. Shale  | 613 |
| Lime        | 261 | Lime        | 617 |
| Shale       | 272 | Blk. Water  | 620 |
| Lime        | 275 | Lime        | 625 |
| Shale       | 285 | Blue Shale  | 630 |
| Lime        | 300 | White Shale | 632 |
| Shale       | 315 | Lime        | 633 |
| Lime        | 369 | Shale       | 646 |
| Water       | 372 | Cap Rock    | 653 |
| Lime        | 385 | Blue Shale  | 665 |
| Shale       | 500 | Broken sand | 680 |
| White Shale | 505 | Bottom hole | 692 |
| Sandy shale | 510 |             |     |
| Blue shale  | 520 |             |     |

Dry