

25-16-21E


Company Texas

Sec. 25 T. 16 R. 21E
Loc. W 1/2 SW 1/4

Farm H.A. Dunn No. 10

Plotted
County Miami

Total Depth 649
Comm. June 25, 1925 - Comp. June 30, 1925 -
Shot or Treated
Contractor
Issued



Casing

20 in.	10 in.
15 1-2	8 1-4 24
12 1-2	6 5-8 610
13 3-8	5 3-16

Elevation 907.0
Production water

Figures Indicate Bottom of Formation

Soil	0	0	Lime	570 - 575
Gravel	3	3	Shale	575 - 595
Shale	10	10	Red Rock	595 - 598
Lime	28	28	Shale	598 - 615
Shale	40	40	Oil Sand	615 - 644
Lime	130	130	Shale	644 - 649.5
Shale	150	150		
Lime	170	170		
Shale	185	185		
Lime	208	208		
Shale	225	225		
Lime	240	240		
Shale	260	260		
Lime	272	272		
Shale Black Water	305	305		
Lime	308	308		
Shale	315	315		
Lime	473	473		
Shale	484	484		
Lime	490	490		
Shale	491	491		
Lime	515	515		
Shale	524	524		
Lime	537	537		
Shale	541	541		