

31-16-222


E.M.V

Company *Texas*  
Farm *C Hollinger* No. 10

Sec. 31 T. 16 R. 22 E  
Loc. SW 1/2 SW 1/4

Total Depth 711  
Comm. *Aug 13 1918* Comp. *sep 9 1918*  
Shot or Treated  
Contractor *Gilmore Elliott*  
Issued

County *Miami*



Casing  
20 in. 10 in.  
15 1-2 8 1-4 *13*  
12 1-2 6 5-8 *530*  
13 3-8 5 3-16 *659*  
*4 20*

Elevation *1019.1*  
Production *oil*

Figures Indicate Bottom of Formation  
*sand 670-708*

*Top soil 12 - 12*  
*Lime 10 - 27*  
*Shale 20 - 47*  
*Lime 25 - 72*  
*Shale 90 - 167*  
*Lime 10 - 177*  
*Shale 50 - 227*  
*Lime 75 - 302*  
*Shale 10 - 312*  
*Water sand 15 - 327*  
*mud 30 - 357*  
*Lime 55 - 412*  
*Shale 10 - 422*  
*sand & gravel 10 - 432*  
*Lime 5 - 437*  
*Shale 90 - 520*  
*sand water 5 - 525*  
*Lime 5 - 530*  
*Shale & broken sand 70 - 600*  
*Hard broken sand & Shale with no pay 572 - 593*

*Lime 10 - 610*  
*Black core 20 - 630*  
*Shale 10 - 640*  
*Lime 10 - 650*  
*white shale 20 - 670*  
*oil sand 38 - 708*  
*Shale 3 - 711*