

United States
 Sec. 11 T. 18 R. 21
 Loc.

02

Company Lemons et al

Farm Hay

No. 1

Total Depth 750

Comm. 4/21/34


Shot or Treated

Contractor

Issued

Comp. 4/ /34

County Miami



Casing
 20 in. 10 in.
 15 1-2 8 1-4
 12 1-2 6 5-8
 13 3-8 5 3-16

Elevation

Production Dry hole

Figures Indicate Bottom of Formation

soil	3	shale	527
lime	25	lime	533
shale	118	shale	546
lime	137	lime	549
shale	161	b shale	553
lime	169	shale	562
shale	207	lime	567
lime	224	shale	585
shale	231	sand	595
lime	261	shale	645
b shale	268	shale	659
lime	291	sand	675
b shale	295 water	shale	725
lime	306	sand	736
shale	420	shale	745
shale	442	sand	750 Dry hole
lime	480		