

Company Black

Sec. 28 T. 18 R. 21
Loc.

Farm Union Central L. I. No.

Total Depth 1040

Comm. 10/12/36


Shot or Treated

Contractor

Issued

Comp.

County Franklin



Casing

20 in. 10 in. → 359
15 1-2 8 1-4 → 401
12 1-4 6 5-8
13 3-8 5 3-16
4 7/8 → 970

Elevation

Production

Figures Indicate Bottom of Formation

1 soil	1
12 25 sand	13
5 gravel	18
9 y clay	27
31 shale	58
15 lime	73
2 shale	75
8 lime	83
10 shale	93
8 lime	105
45 shale	150
20 lime	170
5 shale	175
11 lime	186
1 shale	187
19 lime	206
6 shale	212
3 shale	215
23 lime	238
4 slate	242 water
6 lime	248
3 shale	251
5 lime	256
120 shale	376
25 shale	401
7 lime	408
6 shale	414
28 lime	442
2 shale	444
8 shale	452
4 lime	456
29 shale	485
2 blk shale	487
3 blk shale	490
4 lime	494
18 shale	512
12 lime	524

10 shale	534
21 lime	555
20 shale	575
28 lime	603
47 shale	650
32 slate	682
3 sdy lime	685
30 sdy	715
3 shale	718
3 sdy lime	721 ✓
6 sand	727
28 sdy shale	755
2 lime	757
3 slate	760
33 shale	793
7 shale	800
2 sand	802
41 shale	838
12 lime	850
7 shale	857
20 sand	877
33 shale	910
7 shale dk	917
22 shale	939
14 sand	953
17 sand	970
3 sand	973
14 shale	987
6 blk shale	993
14 lime	1007
10 shale	1017
9 5 lime SAND	1031 → 1026
9 lime	1040

Abandoned
water at 212
oil show at 727
water at 993