

19-19-7C

STATE GEOLOGICAL SURVEY  
WICHITA, KANSAS

State Geological Survey  
WICHITA, BRANCH

MARCH 6, 1958

Frisk well No. 1 (Nanninga #1) - D-1 02/1  
SEC 19, Twp. 19S-Range 7E  
Chase County, Kansas  
On Nanninga farm - In center of North  
line of Southwest quarter

Date Commenced: 2-17-1958  
Date Completed: 3- 3-1958  
Plugged: 3- 4-1958

MAY 23 1977

W-E-L-L L-O-G

<u>FORMATION</u>	<u>FROM</u>	<u>TO</u>	<u>FORMATION</u>	<u>FROM</u>	<u>TO</u>
Lime	0	10	Shale	1083	1106
Lime	10	25	Lime	1106	1125
shells & shale	25	35	Shale	1125	1218
Red Rock	35	54	Lime	1218	1223
Shale	54	64	Shale	1223	1242
Lime	64	73	Lime	1242	1250
Shale	73	120	Shale	1250	1300
Lime	120	140	D.shale	1300	1330
Shale	140	160	Lime	1330	1360
Lime	160	180	Shale	1360	1362
Shale	180	338	Lime	1362	1375
Red Rock	338	347	Shale	1375	1378
Shale	347	394	Lime	1378	1407
Sand	394	417	Broken lime	1407	1425
Shale	417	449	Lime	1425	1522
Lime	449	454	D. Shale	1522	1527
Shale	454	490	Lime	1527	1550
Lime	490	510	Shale	1550	1555
Shale	510	530	Lime	1555	1570
Lime	530	550	Shale	1570	1576
Shale	550	678	Lime	1576	1640
Broken Lime	678	705	Shale Dark	1640	1643
Shale	705	745	Lime	1643	1671
Lime	745	788	Sandy shale	1671	1730
Shale	788	829	Shale	1730	1767
Lime	829	839	Lime	1767	1794
Shale	839	845	Shale	1794	1804
Lime	845	850	Lime	1804	1810
Shale	850	872	Shale	1810	1815
Sandy Lime	872	882	Lime	1815	1821
Sand	882	892	Shale	1821	1826
Lime	892	905	Black lime	1826	1832
Shale	905	915	Lime	1832	1834
Lime	915	948	Red Rock &		
Shell & shale	948	958	Granite shale	1834	1856
Lime	958	972	Sand	1856	1858
Shale	972	993			
Sand	993	1017			
Shale	1017	1025			
Lime	1025	1060			
D. shale	1060	1074			
Lime	1074	1083			

Set 10" @ 394'  
Water 406-415

8" set @ 1125

HFV

Water 1372-1378

HFV @ 800'

Gas 882-892

HFV 938-943

HFV 1007

PLUGGING LOG

Mud to 150'  
Bridge at 150' - 10 sacks cement  
Bridge at 30' - 10 sacks cement  
5 sacks cement at surface

PLUGGING  
SEC. 19 T. 19 R. 7E  
BOOK PAGE 88 LINE 21