

Company- RALPH N, GAFFNEY
Farm- Kling No. 1

SEC. 27 T. 21 R. 12E

NW NW SW

27-21-12E

County Lyon KANSAS

Total Depth. 1917'


Comm. 8-11-59

Comp. 8-21-59

Shot or Treated.

Contractor. Sandlin Drlg. Co.

Issued. 10-24-59



CASING:

7" 85'

Elevation. _____

Production. DRY

Figures Indicate Bottom of Formations.

soil, clay	12
lime shells	30
lime	51
shale	80
lime	90
shale	180
lime	188
shale	192
lime	198
shale	272
lime	314
shale	328
lime	334
shale	360
lime	368
shale	382
lime	387
shale	398
lime	403
shale	425
lime	435
shale	450
lime	458
shale	546
lime	606
shale	611
lime	619
shale	626
lime	641
shale	794
lime	798
shale	820
shale, sdy	986
lime	998
shale	1011
lime	1081
lime, shale	1142
lime	1230
lime, shale	1275
lime	1371
shale w/lime stks	1460
shale	1561
lime	1565
shale	1790
shale w/green stks	1840
shale	1900
sdv shale	1917
Total Depth	