

P10001 ✓

Company Texas

Sec. 14 T.21

Loc. W $\frac{1}{2}$ , NW $\frac{1}{4}$

14-21-22E  
R. 82

20E

(DRL 0909)

Farm M. Odaffer

No. 12

County Anderson

Total Depth 799


Comm.

Comp. 9/5/25

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	12 $\frac{1}{2}$
15 1-2	8 1-4	385
12 1-2	6 5-8	763
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Soil	1	Lime	548
Lime-Shell	2	Shale-Wht	558
Gravel-Clay	12	Lime	567
Shale-Blue	55	Shale-Bl	572
Lime	60	Shale-Lt-Sdy.	582
Shale-Bl	174	Sand-gas	602
Iola-Lime	204	Shale-Bl	630
Shale-Drk.	225	Lime	640
Lime	229	Shale-Bl	645
Shale-Bl	235	Lime	647
Lime	239	Shale-Bl	652
Shale-Bl	253	Lime	665
Lime	263	Shale-Drk.	680
Shale-Bl	278	Lime	685
Lime	285	Shale-Bl	710
Shale-Bl	290	Lime	718
Lime	335	Shale-Dk.	723
Shale-Drk.	341	Lime	729
Lime	361	Shale-Dk	763
Shale-Drk.	366	Shale-Lt.	765
Lime	371	Broken-Sand	775
Shale-Drk.	374	Sand-Oil	795
Lime-Shell	380	Sand-Drk-Shale	799
Shale-Bl	385		
" "	490		
Shale-Lt-Sdy.	545		