

Company Texas

Farm L.E. McGrew

Total Depth 486 $\frac{1}{2}$

Comm.

Shot or Treated

Contractor

Issued


No. 1

Comp. 11/24/20

Sec. 24 T. 21 R. 22

Loc. *6e 4 ne 4*  
S. 1/4 (Ex. 1 1/4 A. NW. Corner)

County Linn



Casing  
20 in. 10 in.  
15 1-2 8 1-4  
12 1-2 6 5-8  
13 3-8 5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

|               |                  |       |                     |
|---------------|------------------|-------|---------------------|
| Soil & Shells | 2                | Lime  | 375                 |
| Lime          | 20               | Shale | 385                 |
| Shale         | 25               | Lime  | 397                 |
| Lime          | 30               | Shale | 415                 |
| Shale         | 36               | "     | 425 <i>water</i>    |
| Lime          | 75               | "     | 437                 |
| Shale         | 90               | Sand  | 446 <i>show oil</i> |
| Lime          | 93               | "     | 483 <i>pay</i>      |
| Shale         | 218              | Shale | 486 $\frac{1}{2}$   |
| Lime          | 226              |       |                     |
| Shale         | 244              |       |                     |
| Lime          | 258              |       |                     |
| Shale         | 309              |       |                     |
| Lime          | 319              |       |                     |
| Shale         | 333              |       |                     |
| Lime          | 338 <i>water</i> |       |                     |
| Shale         | 365              |       |                     |