

Plotted

10-21-22 E ✓

Company Texas

Sec. 10 T. 21 R. 22
Loc. NE 1/4, SW 1/4

Farm Cora Burkhead No. 8

County Linn

Total Depth 527


Comp. 1/19/24

Comm.

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	15
12 1-2	6 5-8	464
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Soil.	2	Lime	430
Clay	13	Drk. Shale	445
Lime-L	55	Lt. Lime	449
D-Shale	63	Drk. Shale	453
Lt. Lime	80	Lt. Shale	470
Blk. Shale	84	Lt. Gas Sand	485
Lt. Lime	110	Oil Sand	492
Blue Shale	240	Shale	495
Lt. Shale	258	Oil Sand	520
Lt. Lime	265	Blk. Shale	527
Lt. Shale	280		
Lt. Lime	295		
Lt. Shale	325		
Drk. Shale	330		
Blue Shale	345		
Lt. Lime	360		
B-Shale	370		
Lt. Lime	375		
Drk. Shale	405		
Ltl Lime	410		
Gray Shale	425		