

Company Texas

Farm Cora Burkhead

No. 1

Total Depth

Comm.

Shot or Treated

Contractor

Issued

Comp. 2/6/20


Sec. 10

T. 21

Loc. E $\frac{1}{2}$ SE $\frac{1}{4}$

R. 22

County Linn



Casing

20 in.	10 in.	
15 1-2	8 1-4	37' 6"
12 1-2	6 5-8	460
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Blk. Soil (soft)	2	Lt. Lime (hard)	398
Yellow Clay-Lime (hard)	16	" Shale (soft)	407
Blk. Shale "	28	" Lime (hard)	414
Blu " "	40	" Shale (soft)	432
Lt. Lime "	89	Drk. Shale "	449
Drk. Shale (soft)	95	Lt. Lime (hard)	467
Lt. Lime (hard)	115	White Shale (soft)	472
Drk. Shale (soft)	119	Blk. " "	476
" Lime (hard)	123	White " "	510
Lt. Shale (soft)	128	Brown Sand "	555
" Lime (hard)	140	Blk.-White Slate-Lime (hard)	561
" Shale (soft)	300		
" Lime (hard)	308		
" Shale (soft)	315		
" Lime (hard)	331		
" Shale (soft)	385		