

Plotted

10-21-22 E

Company Texas

Sec. 10 T. 21 R. 22
Loc. E $\frac{1}{2}$, SE $\frac{1}{4}$

Farm Cora Burkhead No. 4

Total Depth 507

County Linn


Comm.

Comp.

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.
15 1-2	8 1-4 7
12 1-2	6 5-8 452
13 3-8	5 3-16
	4'7/8" 507

Elevation

Production

Figures Indicate Bottom of Formation

Yellow Soil & Clay	7
Lt. Lime Hard	52
" Shale "	58
" Lime "	76
Drk. Shale "	79
Lt. Lime "	85
" Shale "	88
" Lime "	94
" Shale "	97
" Lime "	103
" Shale "	242
Drk. " Soft	252
Lt. Lime Hard	262
" Shale "	269
" Lime "	282

Lt. Shale Hard	340
" Lime "	354
" Shale "	363
" Lime Soft	367
Drk. Shale "	400
Lt. Lime Hard	408
" Shale "	420
" Lime "	428
Drk. Shale "	435
Lt. Lime "	440
" Shale "	446
" Lime "	449
" Sand "	460
" Shale "	481
Sand-Oil Hard & soft	507

Squ