

Plotted *Green*
 10- 21- 22 E 0

Company Texas

Sec. 10 T. 21 R. 22
 Loc. E $\frac{1}{2}$, SE $\frac{1}{4}$

Farm Cora Burkhead No. 5

County Linn

Total Depth 531


Comm.

Comp.

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	9
12 1-2	6 5-8	420
13 3-8	5 3-16	

Elevation

Production

4' 7 7/8" 454

Figures Indicate Bottom of Formation

Yellow Soil & Clay	7	Drk. Shale	soft	381
Lt. Lime	Hard 16	Lt. Lime	hard	387
Drk. Shale	Soft 22	Drk. Shale	"	420
Lt. Lime	Hard 61	Lt. Lime	"	429
Drk. Shale	" 65	" Shale	Soft	434
Lt. Lime	" 96	" "	Hard	440
" Shale	101	" Lime	"	445
" Lime	" 114	Blk. Slate	"	450
" Shale	" 267	Blue Shale	Soft	458
" Lime	Soft 278	" "	"	460
White Shale	Hard 293	White Lime		463
Lt. Lime	" 307	Blk. Shale	"	465
" Shale	" 350	Blue Shale		470
Drk. Shale	Soft 355	White Shale		471
Lt. Lime	Hard 372	" Sand (broken)		475
		Brown Sand	Hard	496
		Lt. Shale	soft	506
		Drk. Sand	"	527
		" Shale	Hard	531