

Plotted *Green*
 10- 21- 22 E 0

Company Texas

Sec. 10 T. 21 R. 22
 Loc. W $\frac{1}{2}$, SE $\frac{1}{4}$.

Farm A.N. Smith
 (Family Oil Co.)

No. 2

Total Depth 521

County Linn


Comm.

Comp. 11/17/20

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.
15 1-2	8 1-4
12 1-2	6 5-8
13 3-8	5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

Clay, Yellow	Soft	16	Lime.	Lt.	Hard	358
Lime, Lt.	Hard	56	Shale	"	"	360
Shale Drk.	"	62	Lime	"	"	375
Lime Lt.	"	82	Shale	Bl	"	400
Shale "	"	87	Lime	Lt.	"	412
Lime "	"	98	Shale	"	"	425
Shale Drk.	"	102	Lime	"	"	432
Lime Lt.	"	108	Shale	Drk.	"	440
Shale, Lt.	"	227	Shale	Lt.	"	443
Lime "	"	231	Lime	"	"	448
Shale "	"	243	Shale	"	"	452
Lime "	"	258	Lime	"	"	455
Shale "	"	280	Shale	Drk.	"	458
Lime "	"	298	"	Lt.	"	480
Shale "	"	328	Sand, Broken	Clay	Soft	515
Lime "	"	331	Shale, Drk.	"	"	521
Shale "	"	348				