

Plotted *21-22E*

Company Texas


Sec. 11 T. 21 R. 22
Loc. SW 1/4

Farm Frank & Rose Early No. 3

County Linn

Total Depth 511
Comm. 5/10/20

Shot or Treated
Contractor
Issued



Casing
20 in. 10 in.
15 1-2 8 1-4 11'6"
12 1-2 6 5-8 453
13 3-8 5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

Blk. Soil	Soft	2	Lt. Lime Hard	343
Yellow Clay	"	7	" Shale Soft	362
Lt. Lime shells,"		11	Drk. Lime Hard	366 water
Lt. Lime	Hard	42	" Shale Soft	396
Blk. Shale	Soft	51	Lt. Lime	403
Lt. Lime	Hard	69	" Shale	413
Drk. Shale	Soft	72	" Lime Hard	422
Lt. Lime	Hard	76	Blk. Shale Soft	427
" Shale	Soft	80	" "	436
Drk. Lime	Hard	86	Lt. Lime Hard	439
Lt. Shale,	Soft	90	" Shale Soft	452
" Lime	Hard	96	Grey Sand	475 Gas
" Shale	Soft	248	Brown Sand	507 Oil
" Lime	Hard	257	Drk. Shale	510
" Shale	Soft	270	" Lime	511
" Lime	Hard	283		
" Shale	Soft	335		