

Company Texas

Sec. 11 T. 21 R. 22
Loc. SW $\frac{1}{4}$

Farm Frank & Rose Early No. 5

Total Depth 508

County Linn


Comm.

Comp. 7/17/20

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	8'
12 1-2	6 5-8	13'
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Soil & Gravel	8	Shale, Drk.	Hard	392
Lime, light, Hard	45	Lime, Lt.	Soft	400
LShale, Drk. Soft	50	Shale "	Hard	412
Lime, Light Hard	76	Lime "	"	420
Shale, " Soft	80	Shale Blk.	"	427 water
Lime, " Hard	86	Lime Lt.	"	431
Shale Drk. "	89	Shale "	"	436
Lime, Lt. "	98	Lime "	"	437
Shale " "	247	Shale "	"	456
Lime " "	256	Sand "	"	475 Gas
Shale " "	268	" " Hard & Soft	"	500 Oil
Lime, " "	282	Shale Drk.	"	507
Shale " "	332	Lime, Blk., Hard		508
Lime " "	344			
Shale Drk. Soft	354			
Lime, Lt. Hard	362			