

Company Texas

Farm D. Mundell

No. 16-W

Total Depth 362

Comm.

Shot or Treated

Contractor


Issued

Comp. 5/26/37

13-21-22E
Sec. 13 T. 21 R. 22

Loc 460' from So & 380' from E
Lines of SW $\frac{1}{4}$

County Linn



Casing

20 in.	10 in.	
15 1-2	8 1-4	23
12 1-2	6 5-8	315
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Soil	Blk.	Sft	2
Riversand	Yel	"	22
Sandy shale	Gr	Med	55
Shale	"	"	75
Sdy Lime & Shale	Drk		85
Shale	Gr	Med	112
Lime	"	"	124
Sdy Shale	"	"	137
Lime	Br	Hd	152
Sdy Shale	Lt	Med	164
Shale	Gr	"	182
Lime-Shells	Drk	"	190
Sdy shale	"	"	202
Lime	Gr	Hd	220
Muddy shale	Drk		228
Lime	Gr	Hd	235
Slate	Blk	Med	237
Sdy Lime	Drk	"	249
Shale	"	"	265

Lime	Gray	Med.	273
Sdy Shale	Drk	"	277
Lime	Br	Hd	290
Blk. Shale	Blk	Med	293
Shale	Gr	Sft	302
Lime	"	Hd	307
Shale	Lt	Sft	315
"	"	"	317
Gas-Sand	"	Med	323
Sand	Gr	"	335
Oil-Sand	Br	Hd	341
"	"	" Med	347
"	"	Drk.	353
"	"	"	356
Sft Brkn Sand	"	"	359
Shale	Blue	"	362