

13P 21 22 E

Sec. 13 T. 21 R. 22  
 Loc. 990' from W. Line & 600'  
 from So. Line SW $\frac{1}{4}$

Company Texas

Farm D. Mundell

No. 22-W

County Linn

Total Depth 356


Comp. 6/25/37

Comm.

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	25
12 1-2	6 5-8	305
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Soil & Sand	Drk	Sft	18	Lime	Gray Med	214
Gravel	Yellow	"	20	Shale	Drk Sft	221
Shale	Gray	Med	67	Lime	Gr Hd	226
Lime-Shells	"	"	75	Slate	Blk Med	228
Sdy Shale	Lt	"	90	Sdy Shale	Drk "	240
Gr.	"	Gr	Sft 104	Shale	" "	255
Lime	"	Lt	Med 113	Lime	Gray Sft	265
Sdy Shale	Gr	"	126	Sdy Shale	Drk Med	271
Lime Shells	"	"	130	Lime	Gray Hd	282
Lime	Br	Hd	140	Sdy Shale	Drk Med	291
Sdy Shale	Lt	Med	165	Lime	Gray Hd	296
" "	Gray	"	185	Sdy Shale	Drk Med	301
Shale	Drk	Sft	195	Shale	Lt Sft	305
Lime	Br	Med	207	Sdy Shale	" Med	308
Shale	Gr	"	211	Sand	" "	320
				Brkn Sand	Gr "	327
				Sand	" "	329 $\frac{1}{2}$
				Oil Sand	Br "	335
				" "	Drk "	347
				Brkn Sand	Bl "	351