

Plotted *Prism*  
 14-21-22E

0 ✓

Company Texas

Sec. 14 T. 21 R. 22  
 Loc. N $\frac{1}{2}$ , NW $\frac{1}{4}$

Farm Martha Kerr

No. 2

Total Depth 467

County Linn


Comm.

Comp. 6/10/20

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	4'6"
12 1-2	6 5-8	400
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Lime, Lt. Hard	22	Lime, White Hard	244
Shale Drk. Soft	28	Shale, Lt. Soft	292
Lime Lt. Hard	33	Lime " Hard	304
Shale " Soft	41	Shale " Soft	309
Lime " Hard	45	Shale Blue "	319
Shale " Soft	60	Lime Lt. Hard	325
Lime " Hard	63	Shale Drk. Soft	348 water
Shale " "	206	Lime Lt. Hard	362
Sand " Soft	211	Shale " "	374
Shale White "	216	Lime " "	378
Lime " Hard	227	Shale Blk. Soft	379
233 Shale Soft	233	Lime Drk. Hard	383
		Shale Blk. Soft	390
		Lime white Med. Hard	393
		Shale Drk.	398
		Shale White	411
		Sand (oil)	425
		Shale Drk. Soft	429
		Sand Bay	460
		Shale Drk.	467