

14-21-22 Plotted *Miller*

Company Texas

Sec. 14 T. 21 R. 22
Loc. S $\frac{1}{2}$, SE $\frac{1}{4}$

Farm (Buster Brown) No. 6
Mundell

Total Depth 486

County Linn


Comm.

Comp. 6/13/22

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.
15 1-2	8 1-4
12 1-2	6 5-8
13 3-8	5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

Soil	6	Shale	403
Lime Shells	9	Lime	411
Lime White	29	Shale	414
Shale	34	Lime	416
Lime	50	Shale	419
Shale	56	Lime	421
Lime	60	Shale	437
Shale	66	Broken Sand	445
Lime	68	Pay Oil Sand	460
Big Shale	230	Shale	480
Lime	238	"	486
Shale	258		
Lime	268		
Shale	325		
Lime	338		
Shale	343		
Lime	346		
Shale	383		
Lime	387		