

Plotted *Crump*
14-21-22 E ✓

Company Texas

Sec. 14 T. 21 R. 22
Loc. S $\frac{1}{2}$, SE $\frac{1}{4}$

Farm (Buster Brown)

No. 7

Mundell

County Linn

Total Depth 465 5/22


Comm.

Comp. 6/23/22

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.
15 1-2	8 1-4
12 1-2	6 5-8
13 3-8	5 3/16 422

Elevation

Production

Figures Indicate Bottom of Formation

Lime Shells	7	Lime	327
Lime	25	Shale	357
Mud	28	Lime	360
Lime	32	Shale	376
Shale	36	Lime	385
"	42	Shale	388 water
Lime	48	"	404
Shale	52	Lime	407
Lime	58	Shale	417
Big Shale	215	Shale White	422
Lime	225	Broken Sand	434
Shale	238	Pay Oil Sand	457
Lime	246	Shale Drk.	465
Shale	298		
Lime	312		
Shale	320		