

24-21-22E

Company Texas

Farm R.A. Randall

Total Depth 508

Comm.

Shot or Treated

Contractor


Issued

No. 10

Comp. 3/27/22

Sec. 24 T. 21 R. 22
 Loc. E $\frac{1}{2}$, NW $\frac{1}{4}$, & E. 28A. W $\frac{1}{2}$, NW $\frac{1}{4}$
 And NW $\frac{1}{4}$, NE $\frac{1}{4}$ & W. 12A. NE $\frac{1}{4}$, NE $\frac{1}{4}$

County Linn



Casing
 20 in. 10 in.
 15 1-2 8 1-4 11
 12 1-2 6 5-8 438
 13 3-8 5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

Soil Br.	Soft	4	Lime	Lt.	Hard	344
Lime-shell	"	11	Shale	"	Sft.	352
" Lt.	Hard	21	Lime	"	Hd	355
Shale Blue	Soft	24	Shale	"	Sft	360
Lime Lt.	Hd.	33	"	Drk	" water	365
Shale Bl.	Soft	39	"	Lt	"	388
Lime Lt.	Hd	59	Lime	"	Hd	395
Shale Bl.	Sft	63	Shale	"	Sft.	407
Lime Lt.	Hd	73	Lime	"	Hd	411
Shale "	Sft.	78	Shale Grey		Sft	416
Lime "	Hd	88	Lime Lt		Hd	420
Shale Big	Sft.	233	Shale Blk.		Sft "	432
Lime Lt.	Hd.	245	" Wht		"	438
Shale "	Sft	269	" Lt		"	445
Lime "	Hd.	283	Sand-Gas		"	465
Shale Bl.	Sft.	333	" Oil		"	505
			Shale Drk.		"	508