

Plotted

19-21-22 E O ✓

Company Texas

Sec. 19

T. 21

R. 22

Loc. S $\frac{1}{2}$ & NW $\frac{1}{4}$

Farm Jas. McGrew (Pillsbury) No. 1

County Linn

Total Depth 495 $\frac{1}{2}$

Comm.


Comp. 2/1/21

1921

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	4 $\frac{1}{2}$ "
15 1-2	8 1-4	7 $\frac{1}{2}$ "
12 1-2	6 5-8	
13 3-8	5 3-16	437

Elevation

Production

Figures Indicate Bottom of Formation

Soil	Blk.	3
Lime		8
"	Lt.	Hard 32
Shale	Drk.	Soft 39
Lime	Lt.	Hard 87
Shale	"	Soft 230
Lime	"	Hard 243
Shale	"	Soft 260
Lime	"	Hard 270
Shale	"	Soft 318
Shale	Drk.	" 322 Gas
"	Lt.	" 330
Lime	"	Hard 342
Shale	"	Soft 350
Lime	"	Hard 357 (gas)
Shale	Drk.	Soft 380 (water)
Lime	Extra	Hard 389
Shale	Drk.	Soft 400
Lime		Hard 408 B.F.S.
Shale	Lt.	" 418

Shale	Blk.	424
"	drk. Soft	431
"	White "	440
Sand	Lt. "	459
"	Brown "	480
Shale	Drk.	495 $\frac{1}{2}$