

19-21-23E Plotted *multi 0*

Company Texas

Sec. 19 T. 21 R. 23
Loc. S $\frac{1}{2}$, NW $\frac{1}{4}$

Farm Jas McGrew (Pillsbury) 2

Total Depth 507

County Linn


Comm.

Comp. 6/10/21

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	90
12 1-2	6 5-8	441'
13 3-8	5 3-16	

Elevation

Production

Figures Indicate Bottom of Formation

Soil	Blk.	Soft	1	Shale Blue	Soft	351
Clay (Yellow)		"	5	Lime Drk.	Hard	355
Lime Lt.		Hard	15	Shale Lt.	Soft	357
Shale Blue		Soft	18	Lime "	Hard	361
Lime Lt.		Hard	38	Shale Drk.	Soft	385
Shale Blue		Soft	44	Lime Lt.	Hard	393
Lime Lt.		Hard	58	Shale Blue	Soft	403
Shale "		Soft	61	Lime Lt.	Hard	412
Lime "		Hard	66	Shale "	"	422
Shale Blue		Soft	70	" Blk.	Soft	430
Lime Lt.		Hard	80	" Grey	"	436
Shale "		Soft	82	" White	"	441
Lime "		Hard	90	" "	"	456
Big-Shale Lt.		Soft	237	Gas-Sand Lt.	Hard	464
Lime Lt. Broken			267	Oil-Sand "	"	497
Lime Brown		Hard	275	Shale Blue	Soft	507
Shale Lt.		Soft	335			
Lime "		Hard	347			