

Company Evans & Crowder

Farm McRay

No. 1

28-21-23 E  
Sec. 28 T. 21 R. 23 E

Loc. SE SW

County Linn

Total Depth 505


Comm.

Shot or Treated

Contractor

Issued

Comp. Dry hole plugged  
Oct. 31, 1944



Casing

|        |        |
|--------|--------|
| 20 in. | 10 in. |
| 15 1/2 | 8 1/4  |
| 12 1/2 | 6 5/8  |
| 13 3/8 | 5 3/16 |

Elevation

Production

Dry

Figures Indicate Bottom of Formation

|             |     |
|-------------|-----|
| soil        | 2   |
| clay        | 10  |
| lime        | 45  |
| shale       | 52  |
| lime        | 67  |
| shale       | 73  |
| lime        | 78  |
| shale       | 81  |
| lime        | 98  |
| shale       | 235 |
| red rock    | 240 |
| lime        | 255 |
| shale       | 275 |
| lime        | 287 |
| B shale     | 345 |
| lime        | 357 |
| P shale     | 370 |
| lime        | 376 |
| L shale     | 406 |
| lime        | 412 |
| FS shale    | 415 |
| lime        | 429 |
| shale black | 455 |
| shale light | 465 |
| sand        | 471 |
| shale       | 505 |

Bottom