


36-21-24E

STATE GEOLOGICAL SURVEY OF KANSAS

Well log

SW SE SE



Location: Sec. 36, T. 21, R. 24.
 Farm Swanson, No. 1, County Linn.
 Company Henderson & Fuller.
 Contractor _____.
 Commenced _____ Completed _____.
 Total depth 755 Elevation _____.
 Initial production Dry hole.
 Correspondence should be addressed to: _____

Log

FORMATION	DEPTH	FORMATION	DEPTH
soil	2	lime	270
clay	22	shale	290
shale	28	sand	305
lime	31	shale	383
oil shale	58	lime	385
coal	61	slate	388
f. clay	63	shale	405
lime	80	shale	435
shale	100	light shale	448
shale	102	water sand	755 (W)
lime	115		Barthesville
sand	133		
B. shale	160		
coal	161		
shale	163		
lime	179		
shale	195		
lime	200		
slate	203		
shale	208		
sand	220		
shale	235		
lime	255		
B. slate	258		
shale	264		