

Company Claude Crowder

Sec. 4 T 22 R. 22E

Farm Cox (Water well)

No. 1

Loc. SE/4

County Linn

Total Depth


Comm.

Shot or Treated

Contractor

Issued

Comp.



Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production

Figures Indicate Bottom of Formation

*Gift From
Claude Crowder*

2	Soil	2
3	Clay & Gravel	5
37	Lime	42
3	Shale Blue	45
4	Shale Black	49
11	Lime	60
3	Shale Dark	63
7	Lime	70
4	Shale Black	74
10	Lime	84
10	Shale Light	94
4	Lime	98
14	Shale White	112
10	Sand	122
10	Shale White	132
50	Shale White Sandy	182
23	Shale White	205
5	Shale Dark	210
5	Shale Light Lime Shells	215
25	Lime Shells	240
25	Lime Shells	265
7	Shale Pink	272
8	Lime	280
10	Shale Light	290
4	Lime Shells	294
16	Shale Light	310
25	Shale Blue	335
15	Lime	350
3	Shale Blue	353
1	Lime	354
6	Shale Dark	360