

C. CROWDER
Laird No. 1

SEC 5 T. 22 R. 23 E.
CS $\frac{1}{2}$ NE

Total Depth. 893
Comm. 5-27-39 Comp. 6-12-39
Shot or Treated.
Contractor.
Issued. 10-17-42

County Linn.



CASING.

NO CASING.

Elevation.

Production. DRY

Figures Indicate Bottom of Formations.

soil and gravel	6
lime	46
shale dark	50
lime	76
shale dark	77
lime	92
shale white	94
lime	105 <i>BKC</i>
shale	122
sand broken	150
sdv shale	160
shale blue	222
broken lime	227
shale white	238
red bed	240
shale blue	250
lime	270
sdv limo	285
shale	288
lime	295
shale	330
limo shells	337
shale	351
limo	364
shale	379
lime	387
shale dark	412
sdv lime	432
lime	447
shale	452
lime	456
shale	465
sdv lime	475
shale blue	490
shale	568
sdv shale	570
broken sand	575
shale	720
sand	736 <i>LBV</i>
shale	770
broken sand	775
slate	790
broken sand	793
chat	798
lime	856
brown sdv lime	862
lime grey	893

Total Depth.

5-22-23E

~~South of NE 1/4~~ South
South 1/2 of NE 1/4 Sec 5 Twp 22 Rge 23

- DR Laird farm
- Cloude Crowder Ft Scott Ks Well no 1
- 6 Soil & gravel 6
- 40 Lime 46
- 4 D Shale 50
- 25 Lime 75
- 2D Shale 77
- 15 Lime 92
- 2 D Shale 94
- 11 Lime 105
- 17 B Shale 122
- 27 Broken Sand 149
- 10 Sandy Shale 159
- 62B Shale 221
- 5 Broken Shale 226
- 11W Shale 248
- 2 Red Bed 250
- 10 B Shale 260
- 20 Lime 280
- 15 Sandy Lime 295
- 3 Shale 302
- 7 Lime 305
- 35 Shale 340
- 7 Lime Shells 347
- 14 Shale 361
- 13 Lime 374
- 15 G Shale 389
- 8 Lime 397
- 24 D Shale
- 20 Sandy Lime 441
- 6 Lime 447
- 5 D Shale 452
- 4 Lime 456
- 9 L Shale 465
- 10 Sandy Lime 475
- 15 B Shale 490
- 12 L Shale 502
- 45 B Shale 547
- 3 L Shale 550
- 18 B Shale 568
- 2 Shale 570
- 5 Broken Sand 575
- 75 B Shale 650
- 40 L Shale 690
- 20 G Shale 710
- 10 B Shale 720
- 16 Sand 736
- 4 L Shale 740
- 25 B Shale 765
- 5 B Shale 770
- 5 Broken Sand 775
- 15 B Shale 790
- 3 Broken Sand 795
- 5 Chat 798
- 95 Lime 893
- Bottom of hole

MAY 23 1977

State Geological Survey
WICHITA, BRANCH

PLUGGING
 FILE SEC 5-T-22R-23E
 BOOK PAGE 66 LINE 27

