

Company Claude Crowder

Farm Mantey

No. 1

~~14 22 23E~~
Sec. 11 T. 22 R. 23E
Loc. NW, W 3/4 N/2
County Linn

11-22-238

Total Depth


Comm.

Shot or Treated

Contractor

Issued

Comp.



Elevation

Production

Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Figures Indicate Bottom of Formation

2	Soil	2	
10	Clay	12	
16	Shale	28	
1	Coal	29	
1	Shale	30	
14	Lime Brown Hard	44	
12	Shale	56	
5	Lime	61	
4	Shale	65	
11	Sandy Shale	76	Oil Show
24	Shale	100	
15	Lime-White Soft	115	
9	Lime	124	
2	Shale	126	Little Gas
4	Lime	130	
57	Shale Light	187	
10	Sand Gray Soft	197	
6	Shale	203	
15	Sand-Squirrel	218 ^x	Oil Show
16	Shale Blue	234	
2	Lime Hard	236	
49	Shale	285	
3	Lime Hard	288	
3	Shale Dark	291	
3	Sand Soft	294	Little Gas
59	Shale Light	353	
29	Sand-Brown Soft	382	Oil Show
13	Shale Dark	395	
5	Slate Black	400	
10	Shale Blue	410	
5	Slate Dark	415	
15	Shale Light-Sandy	430	
5	Sandy Lime	435	
29	Lime Gray Hard	464	
2	Shale	466	
12	10" Casing Set	478	
22	Lime Lt. Gray Soft	500	
95	Lime Gray Hard	595	
3	Shale Blue	598	
11	Lime Hard	609	
4	Sand Brown Soft	613	
2	Lime Hard	615	

Gift From
Claude Crowder

Company

Sec. 14 T. 22 R. 23E

Loc.

Farm

No.

County

Total Depth


Comm.

Shot or Treated

Contractor

Issued

Comp.



Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production

Figures Indicate Bottom of Formation

3	Lime Hard	618
32	Sand Gray	650
45	Lime Gray Hard	695
5	Shale Light	700
90	Lime Hard	790
10	Sandy Lime	800
30	Sandy Lime Soft	830
10	Sandy Lime Med	840
16	Sandy Lime Hard	856

Gift From
Claude Crowder