

Company

Farm Hiatt, Ed

No. 2

Total Depth 833

Comm.

Shot or Treated


Contractor

Issued

Comp.

Sec. 15 T. 22 R. 23
Loc. *28?*

County Linn



Casing
20 in. 10 in.
15 1-2 8 1-4
12 1-2 6 5-8
13 3-8 5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

2 soil	2	22 lime	292
3 gravel and clay	5	68 blue shale	355
1 lime	6	25 lime	380
4 gravel	10	6 shale	386
7 lime	17	6 lime water	392
2 shale	19	8 sand	400
20 lime	39	32 shale ls	432
5 shale blue	44	18 lime	450
3 lime	47	8 shale light	458
7 shale dark	54	1 lime water	499
16 lime	70	59 shale	508
4 dark shale	74	2 lime	510
6 lime	80	66 dark shale	576
5 blue shale	85	2 lime	578
21 lime	106	122 shale blue and black	700
147 shale	253	70 shale white	770
2 red rock	255	24 dark shale	794
6 lime	261	7 dark sandy shale	801
9 light shale	270	32 black shale	833

BKC
Ken
Al
Bld
Pow
Up
FS
Arb