

Company Claude Crowder

Sec. 26 T. 22 R. 23E

Farm Uri

No. 2

Loc. NE/4

County Linn

Total Depth


Comm.

Shot or Treated

Contractor

Issued

Comp.



Elevation

Production

Gift From
Claude Crowder

Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Figures Indicate Bottom of Formation

15	Soil & Gravel	15
5	Lime	20
5	Shale Blue	25
12	Lime	37
4	Shale Light	41
2	Lime	43
4	Shale Light	47
9	Lime	56
11	Shale Light	67
28	Lime	95
35	Shale Blue	130
52	Shale Light	182
5	Shale Pink	187
20	Shale Blue	207
12	Shale Lime	219
11	Shale Blue	230
15	Lime	245
7	Shale Blue	252
4	Lime	256
34	Shale Light	290
10	Shale Dark	300
23	Lime	323
8	Shale Blue	331
5	Lime	336
3	Shale Dark	339
10	Sand	349
19	Shale Blue	368
14	Shale Light	382
18	Lime	400
9	Shale Black	409
5	Lime	414
6	Shale Dark	420
30	Shale Light	450
40	Shale Dark	490
23	Shale Light	513
2	Lime	515
5	Shale Black	520
10	Shale Gray	530
15	Shale Dark	545
5	Shale Light	550
10	Shale Dark	560
6	Shale Blue	566
4	Lime	570
2	Slate Black	572

Company

Farm

No. 2

Sec. 26 T. 22 R. 23

Loc.

County

Total Depth

Comm.

Comp.

Shot or Treated

Contractor

Issued

Casing

20 in.

10 in

15 1/2


8 1/4

12 1/2

6 5/8

13 3/8

5 3/16



Elevation

Production

Figures Indicate Bottom of Formation

5 Shale Gray
7 Sand Broken
12- Shale Light

577
584
596 1/2

1611 From
Claude Crawford