

Company Claude Crowder

Farm Earl Davis

No.

Sec. 30 T. 22 R. 23E

Loc. NE/4

County ~~Allen~~ Linn

30-22-23E

Total Depth


Comm.

Comp.

Shot or Treated

Contractor

Issued



Elevation

Production

Casing	
20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Figures Indicate Bottom of Formation

2	Soil	2
2	Gravel	4
58	Lime	62
2	Blue Shale	64
5	Lime	69
2	Gray Shale	71
7	Lime	78
3	Gray Shale	81
4	Lime	85
7	Blue Shale	92
3	Lime	95
3	Blue Shale	98
14	Lime	112
10	Blue Shale	122
6	Lime	128
104	Blue Shale	232
33	Gray Shale	265
7	Red Shale	272
33	Lime	305
12	Green Shale	317
3	Lime	320
45	Blue Shale	365
25	Lime	390
4	Blue Shale	394
6	Lime	400
30	Blue Shale	430
8	Gray Shale	438
19	Lime	457
7	Black Shale	464
5	Lime	469
51	Light Shale	520
30	Blue Shale	550
5	Light Shale	555
15	Blue Shale	570
2	Lime	572
8	Blue Shale	580
70	Light Shale	650
2	Lime	652
13	Gray Shale	665
5	Blue Shale	670
20	Light Shale	690
5	Dark Shale	695
35	Light Shale	730
90	Dark Shale	820

Gift From  
Claude Crowder

Company

Sec. 30 T. 22 R. 23E

Farm

No.

Loc.

County

Total Depth


Comm.

Shot or Treated

Contractor

Issued

Comp.



Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production

Figures Indicate Bottom of Formation

8	Mis Lime	828
3	Broken Lime	831
2	Lime	833

Gift From  
Claude Crowder