

CARBON WELL # 3

6-2-13

About 200 feet N. of house S.W. $\frac{1}{4}$ - N.E. $\frac{1}{4}$

Sec. 4 Twp. 22 S. R. 24 E

soil	8	
soap	30	
lime shells	70	
shale	94	
"	104	
O. lime	132	
blk. slate	134	gas
shale	170	
sand	172	gas
shale	233	
lime	235	
shale	272	
lime shells	273	
shale	293	
fire clay	303	4 7/8 casing
shale	342	
sandy	380	gas
slate	382	little water

Company Claude Crowder

Sec. 4 T. 22 R. 24E

Farm Chas Carbon


No. 3

Loc. 200 N of house SW NE

County Linn

Total Depth
Comm. 1913
Shot or Treated
Contractor
Issued

Comp.



Casing	
20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production

Figures Indicate Bottom of Formation

*Gift From
Claude Crowder*

8	Soil	8	
22	Soap	30	
40	Lime Shells	70	
24	Shale	94	
10	"	104	
28	O Lime	132	
2	Blk Slate	134	gas
36	Shale	170	
2	Sand	172	gas
61	Shale	233	gas
2	Lime	235	
37	Shale	272	
1	Lime Shells	273	
20	Shale	293	
10	Fire Clay	303	4 7/8 casing
39	Shale	342	
38	Sandy	380	gas
2	Slate	382	salt water

Fletcher So. East Corner

	casing in hole	298	
5	Shale	303	
6	Sand	309	gas
10	Shale	319	
13	Sand	332	gas