

1-22-24E ✓

Company

Sec. 1 T. 22 R. 24

Farm Kalje

No. 2

Loc. SW

County Linn

Total Depth 421


Comp.

Comm.

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.
15 1-2	8 1-4
12 1-2	6 5-8
13 3-8	5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

2 soil	2	5 blk slate	230
20 clay	22	10 blue shale	240
3 shale blue	25	2 lime	242
10 lime	35	18 light shale	260
15 shale	50	55 shale blue	315
A 15 lime	65	2 lime	317
B 55 shale blue	120	18 shale	335
25 lime	145	3 slate blk gas	338
D 5 blue shale	150	45 shale white	383
2 lime	152	8 blk shale	391
8 sand water	160	7 blue shale	398
✓ 30 blue shale	190	7 blk lime	405 gas X
3 slate blk	193 gas X	8 blk slate	413 gas X
12 slate light	205	5 blue slate	418
FS 20 lime	225 gas set pipe X	Bottom Hole	421
	at 234 to 6'		