

Company Claude Crowder

Sec. 4 T. 22 R. 24E

Loc. SWc W2 NW/4

Farm C.A. Cook

No.

County Linn

Total Depth


Comm. Aug 9, 1939

Comp. Aug 17, 1939

Shot or Treated

Contractor Gause & Evas

Issued



Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production

Gift From  
Claude Crowder

Figures Indicate Bottom of Formation

8	Soil & Clay	8	
37	Shale Light	45	
5	Shale Dark	50	
20	Lime	70	2 bailers water hr. @ 60 ft.
10	Shale Dark	80	
10	Lime Brown	90	Run 287' 6 1/4 Casing
6	Sand	96	
6	Shale	102	
13	Sandy Lime	115	
13	Shale Light	128	
20	Lime	148	
4	Slate Blk	152	
48	Shale Light Sandy	200	
35	Sand Dry	235	
15	Shale Dark	250	
3	Lime	253	
15	Shale Dark	268	
2	Lime	270	
5	Shale & Coal	275	
8	Sand	283	
17	Sandy Shale	300	
20	Shale & Coal	320	Hole made 100' water at 330
40	Shale Light	360	
5	Sand Broken	365	Gas at 370
31	Sand	396	

at 70'

Run 396' 2" Pipe  
Perforation ?

Black Packer 360 can be swabbed to bottom