Company Claude Crowder

Sec. 5 T. 22 R. 24E

Loc. NE/4

Farm Ben Murray No. 2

County Linn


Total Depth

Comm. 10-28-39 Comp.

Shot or Treated

Contractor

Issued



Elevation

Production

Casing	
20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Figures Indicate Bottom of Formation

Gift From Claude Crowder

24	Soil & Clay	24	
16	" Broken Lime	40	
10	Shale	50	
5	Lime	55	
8	Dark Shale	63	
7	Sand	70	
7	Light Shale	77	
13	Sandy Lime	90	
12	White Shale	102	
20	Lime	122	
5	Shale	127	
5	Lime	132	
18	" Sandy	150	Prue 18 ft.
25	Shale Sandy	175	
35	Sand	210	
35	Dark Shale	245	
2	Lime	247	
8	Dark Shale	255	
10	Light Shale	265	
12	Blue Slate	277	
3	Light Shale	280	
10	Blk Shale	290	Run 290' 6 1/4
5	Light Shale	295	
15	Sandy Shale	310	
10	Brown Sand	320	Gas 315
5	Broken Sand	325	
20	White Shale	345	
35	Sand	380	Gas 413
8	White Slate	388	
8	Blk Slate	496	Water
8	Light	504	
23	Sand	527	
17	Shale	544	
2	Lime Miss	546	