

Company Claude Crowder

Sec. 22 T. 22 R. 24E

Farm Moska

No.

Loc. NE/4 SW/4

County Linn

Total Depth


Comm. 8-16-1907

Comp.

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production

Figures Indicate Bottom of Formation

*Gift From  
Claude Crowder*

32	Clay	32	
10	Lime	42	
23	Soap	65	
15	Lime	80	
10	Sand	90	Oil
50	Shale	140	Oil
15	Lime	155	
8	Soap	163	
20	Sand	183	Gas
10	Sand	193	Gas
10	Soap	203	
20	Lime	223	
4	Blk Slate	227	Wtr
4	Soap	231	
5	Lime	236	
4	Soap	240	Case 6 1/4
40	Shale	280	
20	Sand	300	Oil
35	Shale	335	
1	Lime	336	
1	Blk Slate	337	Gas
40	Shale	377	
1	Lime	378	
42	Shale	420	
65	Sand	485	
15	Sand	500	Wtr