Company


Farm Cross No.

Sec. 23 T. 22 R. 24
Loc. NE¼

23-22-24E

Total Depth 1400
Comm. Comp.
Shot or Treated
Contractor
Issued

County Linn



Elevation

Production

Casing

20 in.	10 in.
15 1-2	8 1-4
12 1-2	6 5-8
13 3-8	5 3-16

Figures Indicate Bottom of Formation

"This is the well the dentist had in mind"

Soil & Soap	20	20	
Sand & oil	120	140	X
Sandy Soaps	55	75	
Lime, hard	10	85	
Soapstone	45	130	
Coal, trace	—	—	
Lime, water	30	160	W
Soapstone	10	170	
Sand (Oil)	10	180	X
Soapstone	15	195	
Soap, sticky	10	205	
Sand oil	3	208	X
Fire clay	2	210	
Oswego lime	38	248	
Bl. Slate	2	250	
Fire Clay	3	253	
Lime	10	263	
Shale, soap	3	266	
Sand	74	340	
Lime	5	345	
Shale	10	355	
Lime, bl. slate	6	361	
Slate	4	365	
Lime	15	400	
Slate	48	432	
Bl. Slate	2	434	
Soapstone	12	446	
Sand, shale	20	466	
Sand	78	544	
Sand, salt water	20	564	W
Slate	31	595	
Flint	7	602	Miss
Miss. Lime	62	664	
Blue Mud	40	704	
Lime & flint	81	785	
Lime & sand	80	865	
Green Shale	121	986	
Lime	14	1000	

Lime and sand 400 1400