

(K/11)

Lewis Hedman Farm.

Well no. 1 SW corner.

Started Feb. 3, 1935

E  $\frac{1}{2}$  NE  $\frac{1}{4}$  of Sec 26-22-24

1	soil	1	
14	yellow clay	15	
3	sand stone	18	
20	shale, blue	38	
20	lime	58	
2	shale dark	60	Water
8	lime	68	
30	shale, blue	98	
7	lime shells	105	
29	shale light	134	
9	lime	143	
25	light shale	168	
18	lime	186	
9	sand, oil showing	195	
	Reduced $6\frac{1}{4}$ at 260'		
43	shale, blue	238	
19	lime	257	
5	shale, dark.	262	Water
4	lime	266	
<del>24</del>	shale blue	290	✓
10	sand	300	
5	lime	305	
4	white shale	309	
9	shale, blue	318	
12	lime	330	little
5	slate black	335	gas
4	lime	339	
6	shale blue	345	
5	sand-oil showing	350	
25	shale blue	375	
2	lime	377	
13	shale blue	390	
5	black shale	395	
40	light shale	435	
4	lime black	439	
3	slate black	442	little gas
3	shale lime black	445	

27	Shale, white	472
16	Shale, blue	488
2	lime	490
30	light shale	520
5	broken sand	525
9	sand water	534

Dry hole, plugged since  
 Porter, State pluggin, Pleasanton,  
 Kansas. Feb. 15 - 1935

Gillham + Lockett, Hillers.  
 Hoffman, Smith + Evans, Ladd.