

Company Claude Crowder

Sec. 1 T. 22 R. 25E

Farm John Eby

No. 1

Loc. N/2 NW/4

County Linn

Total Depth


Comm.

Shot or Treated

Contractor

Issued

Comp.



	Casing	
20 in.	10 in	
15 1/2	8 1/4	
12 1/2	6 5/8	
13 3/8	5 3/16	

Elevation

Production

*Gift From
Claude Crowder*

Figures Indicate Bottom of Formation

3	Soil	3	
35	Blue Shale	38	
6	Sand Stone	44	
31	Shale	75	
6	Sand Rock	81	
1	Shale	82	
10	Lime	92	
2	Shale	94	
10	Sand	104	Oil
36	Shale	140	
15	Lime	155	
10	Blue Shale	165	
5	Lime	170	
20	Shale	190	Water
10	Sand	200	Oil
10	Shale	210	
21	O Lime	231	
2	Blk Slate	233	Gas Oswego
5	Lime	238	
52	Shale	290	
10	Sand	300	Oil
60	Shale	360	
2	Lime Hard	362	
118	Blk Shale	480	Salt Water

Set 410' 4 7/8 Casing
Reduced hole 111'